

## Utility Conflict Report

<b>OWNER</b>	<b>Utility</b>	CPS	<b>Corridor</b>	RIGSBY	<b>SITE PHOTOS</b>	
	<b>Contact</b>	JAKE MARTINEZ	<b>ID</b>	2069		
<b>GENERAL INFO</b>	<b>Utility</b>	ELECTRIC				
	<b>Size and Material</b>	STANDARD POWER POLE, TIMBER				
	<b>Utility Conflict Description</b>	POLE WITHIN PROPOSED SIDEWALK				
	<b>Longitudinal or Crossing</b>	CROSSING				
	<b>Placement Relative to ROW</b>	INSIDE				
<b>LOCATION</b>	<b>Sheet No.</b>	325				
	<b>Station Origin</b>					
	<b>Start Station</b>	655+42.17	<b>End Station</b>			
	<b>Start Offset</b>	9.45	<b>End Offset</b>			
	<b>Latitude</b>	29.398164219	<b>Longitude</b>	-98.434128236999996		
<b>SUE</b>	<b>Level of Investigation Req'd</b>	NONE				
	<b>Test Hole No</b>	N/A				
	<b>Test Hole Depth</b>	N/A				
<b>RESOLUTION</b>	<b>Recommended Action</b>	ACCOMMODATE - RELOCATION				
	<b>Estimated Resolution Date</b>					
	<b>Resolution Status</b>	UTILITY COORDINATION IN PROGRESS				
	<b>Comment</b>	INSUFFICIENT CLEARANCE PER PROWAG, 48" CLEARANCE REQUIRED. 41" BACK OF CURB TO FACE OF POLE, 11" POLE DIA, 21" BACK OF POLE TO ROW (BACK OF SIDEWALK)				
<b>Date Collected</b>		8/14/2017 11:03:44 AM		<b>Date Modified</b> 11/27/2017 10:45:19 AM		

