

## Utility Conflict Report

<b>OWNER</b>	<b>Utility</b>	CPS	<b>Corridor</b>	RIGSBY	<b>SITE PHOTOS</b>
	<b>Contact</b>	JAKE MARTINEZ	<b>ID</b>	238	
<b>GENERAL INFO</b>	<b>Utility</b>	ELECTRIC			
	<b>Size and Material</b>	STANDARD POWER POLE, TIMBER			
	<b>Utility Conflict Description</b>	POLE WITHIN PROPOSED SIDEWALK			
	<b>Longitudinal or Crossing</b>	CROSSING			
	<b>Placement Relative to ROW</b>	INSIDE			
<b>LOCATION</b>	<b>Sheet No.</b>	328			
	<b>Station Origin</b>				
	<b>Start Station</b>	662+03.92	<b>End Station</b>		
	<b>Start Offset</b>	9.54	<b>End Offset</b>		
	<b>Latitude</b>	29.398172594	<b>Longitude</b>	-98.436206193000004	
<b>SUE</b>	<b>Level of Investigation Req'd</b>	NONE			
	<b>Test Hole No</b>	N/A			
	<b>Test Hole Depth</b>	N/A			
<b>RESOLUTION</b>	<b>Recommended Action</b>	ACCOMODATE - RELOCATION			
	<b>Estimated Resolution Date</b>				
	<b>Resolution Status</b>	UTILITY COORDINATION IN PROGRESS			
	<b>Comment</b>	INSUFFICIENT CLEARANCE PER PROWAG, 48" CLEARANCE REQUIRED. 31" BACK OF CURB TO FACE OF POLE, 14" POLE DIA, 35" BACK OF POLE TO ROW (BACK OF SIDEWALK)			
<b>Date Collected</b>		11/8/2017 1:33:26 PM	<b>Date Modified</b>		11/29/2017 9:22:56 AM

