



Pavement Report

GENERAL INFO	<p>ID 208</p> <p>Corridor BS 123B</p> <p>Latitude +29.578706</p> <p>Longitude -97.964705</p> <p>Google Maps Hyperlink <a +29.578706,-97.964705"="" href="http://local.google.com/maps?q=">http://local.google.com/maps?q="+29.578706,-97.964705</p> <p>Field Notes CPL CORNER - full lane width (16') - full width of cedar st. - 21' at salon corner along BU 123 - 34' deep into cedar - pave repai mh</p>
UTILITY DETAILS	<p>Utility Pavement Repair</p> <p>Owner TXDOT</p> <p>Type Vertical</p>
SITE PHOTOS	<div style="display: flex; justify-content: space-around; text-align: center;"> <div style="width: 30%;"> <p>Photo 1</p>  </div> <div style="width: 30%;"> <p>Photo 2</p>  </div> <div style="width: 30%;"> <p>Photo 3</p> </div> </div>
<p>Date Collected 11/7/2017 3:53:27 PM Date Modified 12/11/2017 12:12:38</p>	