

Utility Conflict Report

| | | | | | |
|-----------------------|-------------------------------------|--|----------------------|---------|-----------------------|
| OWNER | Utility | CPS | Corridor | BANDERA | SITE PHOTOS |
| | Contact | JAKE MARTINEZ | ID | 3189 | |
| GENERAL INFO | Utility | ELECTRIC | | | |
| | Size and Material | STANDARD POWER POLE, TIMBER | | | |
| | Accessible Route | ASSET IS OUTSIDE ACCESSIBLE ROUTE | | | |
| | Longitudinal or Crossing | CROSSING | | | |
| | Placement Relative to ROW | INSIDE ROW | | | |
| LOCATION | Sheet No. | | | | |
| | Station | | | | |
| | Offset | | | | |
| | Latitude | +29.521476 | | | |
| | Longitude | -98.63850 | | | |
| SUE | Level of Investigation Req'd | NONE | | | |
| | Test Hole No | N/A | | | |
| | Test Hole Depth | N/A | | | |
| RESOLUTION | Recommended Action | NO CONFLICT | | | |
| | Estimated Resolution Date | 8/28/2018 | | | |
| | Resolution Status | NO RESOLUTION WAS REQUIRED | | | |
| | Comment | Pole diameter = 12" | | | |
| | | Back of sidewalk to pole = 4" Underground cable warning on pole No overhead lines attached to pole | | | |
| Date Collected | | 8/16/2018 11:05:23 AM | Date Modified | | 11/28/2018 6:59:12 AM |

