

Utility Conflict Report

| | | | | | | | |
|-----------------------|-------------------------------------|---|-----------------|----------------------|--------------------|-----------------------|--|
| OWNER | Utility | CPS | Corridor | BANDERA | SITE PHOTOS | | |
| | Contact | BILL FEY | ID | 3217 | | | |
| GENERAL INFO | Utility | GAS | | | | | |
| | Size and Material | STANDARD GAS VALVE, CAST IRON | | | | | |
| | Accessible Route | ASSET IS OUTSIDE ACCESSIBLE ROUTE | | | | | |
| | Longitudinal or Crossing | CROSSING | | | | | |
| | Placement Relative to ROW | INSIDE ROW | | | | | |
| LOCATION | Sheet No. | 242 | | | | | |
| | Station | 1404+75 | | | | | |
| | Offset | 55 | | | | | |
| | Latitude | +29.500532 | | | | | |
| | Longitude | -98.62456 | | | | | |
| SUE | Level of Investigation Req'd | NONE | | | | | |
| | Test Hole No | N/A | | | | | |
| | Test Hole Depth | N/A | | | | | |
| RESOLUTION | Recommended Action | NO CONFLICT | | | | | |
| | Estimated Resolution Date | | | | | | |
| | Resolution Status | NO RESOLUTION WAS REQUIRED | | | | | |
| | Comment | Top of valve to surface = 2'-10" Lid thickness = 1 1/2" Face of wall to valve = 6'-9" | | | | | |
| Date Collected | | 8/17/2018 1:33:48 PM | | Date Modified | | 12/18/2018 4:46:48 PM | |

