

Utility Conflict Report

OWNER	Utility	CPS	Corridor	BANDERA	SITE PHOTOS		
	Contact	JAKE MARTINEZ	ID	3218			
GENERAL INFO	Utility	ELECTRIC					
	Size and Material	STANDARD POWER POLE, TIMBER					
	Accessible Route	ASSET IS OUTSIDE ACCESSIBLE ROUTE					
	Longitudinal or Crossing	CROSSING					
	Placement Relative to ROW	INSIDE ROW					
LOCATION	Sheet No.						
	Station						
	Offset						
	Latitude	+29.500554					
	Longitude	-98.62453					
SUE	Level of Investigation Req'd	NONE					
	Test Hole No	N/A					
	Test Hole Depth	N/A					
RESOLUTION	Recommended Action	NO CONFLICT					
	Estimated Resolution Date	8/28/2018					
	Resolution Status	NO RESOLUTION WAS REQUIRED					
	Comment	Corner of wall to pole = 8'-10" No pole ID Back of culvert concrete safety end treatment to pole = 7'-4"					
Date Collected		8/17/2018 1:36:23 PM		Date Modified		11/28/2018 6:59:12 AM	

