

## Utility Conflict Report

<b>OWNER</b>	<b>Utility</b>	SAWS	<b>Corridor</b>	SW MILITARY	<b>SITE PHOTOS</b>
	<b>Contact</b>	ANN PECHE	<b>ID</b>	4225	
<b>GENERAL INFO</b>	<b>Utility</b>	SANITARY SEWER			
	<b>Size and Material</b>	STANDARD MANHOLE, CAST IRON			
	<b>Accessible Route</b>	ASSET IS INSIDE ACCESSIBLE ROUTE			
	<b>Longitudinal or Crossing</b>	CROSSING			
	<b>Placement Relative to ROW</b>	INSIDE ROW			
<b>LOCATION</b>	<b>Sheet No.</b>	168			
	<b>Station</b>	725+31.91			
	<b>Offset</b>	16.5894			
	<b>Latitude</b>	+29.356609			
	<b>Longitude</b>	-98.49911			
<b>SUE</b>	<b>Level of Investigation Req'd</b>	NONE			
	<b>Test Hole No</b>	N/A			
	<b>Test Hole Depth</b>	N/A			
<b>RESOLUTION</b>	<b>Recommended Action</b>	NO CONFLICT			
	<b>Estimated Resolution Date</b>	11/21/2018			
	<b>Resolution Status</b>	NO RESOLUTION WAS REQUIRED			
	<b>Comment</b>	Back of curb to manhole = 4'-0" Sidewalk width = 6'-1" Manhole adjacent to face of wall Electric wiring for lighting attached to manhole lid Lid flange thickness = 1.5" Overall lid thickness = 1.5" Bottom of cone to surface = 10"			
	<b>Date Collected</b>		8/7/2018 9:58:06 AM	<b>Date Modified</b>	

