

Utility Conflict Report

OWNER	Utility	CPS	Corridor	SW LOOP 410	SITE PHOTOS		
	Contact	JAKE MARTINEZ	ID	7002			
GENERAL INFO	Utility	GAS					
	Size and Material	STANDARD GAS VALVE, CAST IRON					
	Accessible Route	ASSET IS INSIDE ACCESSIBLE ROUTE					
	Longitudinal or Crossing	CROSSING					
	Placement Relative to ROW	INSIDE ROW					
LOCATION	Sheet No.						
	Station	295+81.28					
	Offset	-18.6223					
	Latitude	+29.377260					
	Longitude	-98.64031					
SUE	Level of Investigation Req'd	NONE					
	Test Hole No	N/A					
	Test Hole Depth	N/A					
RESOLUTION	Recommended Action	NO CONFLICT					
	Estimated Resolution Date	8/13/2018					
	Resolution Status	NO RESOLUTION WAS REQUIRED					
	Comment	2 gas valves in concrete riprap (3 and 4 of 4) Top of valves to surface = 0" Edge of pavement to front edge of riprap = 6'-3"					
Date Collected		8/2/2018 8:28:06 AM		Date Modified		8/14/2018 4:38:26 PM	

