

## Utility Conflict Report

<b>OWNER</b>	<b>Utility</b>	SAWS	<b>Corridor</b>	NOGALITOS	<b>SITE PHOTOS</b>		
	<b>Contact</b>	ANN PECHE	<b>ID</b>	3066			
<b>GENERAL INFO</b>	<b>Utility</b>	WATER					
	<b>Size and Material</b>	STANDARD WATER VALVE, CAST IRON					
	<b>Accessible Route</b>	ASSET IS INSIDE ACCESSIBLE ROUTE					
	<b>Longitudinal or Crossing</b>	CROSSING					
	<b>Placement Relative to ROW</b>	INSIDE ROW					
<b>LOCATION</b>	<b>Sheet No.</b>	86					
	<b>Station</b>	136+43.20					
	<b>Offset</b>	25.5205					
	<b>Latitude</b>	+29.394001					
	<b>Longitude</b>	-98.51718					
<b>SUE</b>	<b>Level of Investigation Req'd</b>	NONE					
	<b>Test Hole No</b>	N/A					
	<b>Test Hole Depth</b>	N/A					
<b>RESOLUTION</b>	<b>Recommended Action</b>	NO CONFLICT					
	<b>Estimated Resolution Date</b>						
	<b>Resolution Status</b>	NO RESOLUTION WAS REQUIRED					
	<b>Comment</b>	Top of valve to surface = 6 1/2" Box to back of sidewalk = approx. 2'-6" Box to back of curb = 4'-2" Sidewalk width = 8'-2" No lid Replace meter box only					
<b>Date Collected</b>		7/11/2018 11:44 AM		<b>Date Modified</b>		8/15/2018 12:40:05 PM	

