

Utility Conflict Report

OWNER	Utility	CPS	Corridor	NOGALITOS	SITE PHOTOS
	Contact	JAKE MARTINEZ	ID	4010	
GENERAL INFO	Utility	GAS			
	Size and Material	STANDARD GAS VALVE, CAST IRON			
	Accessible Route	ASSET IS INSIDE ACCESSIBLE ROUTE			
	Longitudinal or Crossing	CROSSING			
	Placement Relative to ROW	INSIDE ROW			
LOCATION	Sheet No.				
	Station	104+75.60			
	Offset	-34.7585			
	Latitude	+29.387202			
	Longitude	-98.52335			
SUE	Level of Investigation Req'd	NONE			
	Test Hole No	N/A			
	Test Hole Depth	N/A			
RESOLUTION	Recommended Action	NO CONFLICT			
	Estimated Resolution Date	8/13/2018			
	Resolution Status	NO RESOLUTION WAS REQUIRED			
	Comment	Top of valve is 3'-9" below the surface Lid thickness = 1 1/2" Back of curb to valve = 1'-8 1/2"			
Date Collected 7/2/2018 10:16:47 AM Date Modified 8/14/2018 4:38:26 PM					

