


## Data Collection Report

GENERAL INFO	<b>LOCID</b>	9	<b>Latitude</b>	+26.485944
	<b>Highway</b>	US 83	<b>Longitude</b>	-99.056781
	<b>County</b>	Starr	<b>Element</b>	Drainage
	<b>CSJ</b>	0038-06-047		
	<b>Map Link</b>	<a href="https://maps.google.com/maps?t=h&amp;q=+26.485944,-99.056781">https://maps.google.com/maps?t=h&amp;q=+26.485944,-99.056781</a>		
	<b>Field Notes</b>	<p>NBI-003806030 cast in place          Upstream-8-8'2"x4' wall thickness=6"          Outfall-7'x4' wall thick-6"          Boxes drop vertically and turns horizontally at outfall</p> <p>5th from south side-fill invert? 1st photo          Guardrail=31"</p>		
SITE PHOTOS				
<b>Photo 1</b>				
<b>Date Collected</b>		11/13/2017 2:32:42 PM	<b>Date Modified</b>	
			11/13/2017 2:45:24 PM	

## Data Collection Report

SITE PHOTOS



**Photo 2**



**Photo 3**

**Date Collected** 11/13/2017 2:32:42 PM

**Date Modified** 11/13/2017 2:45:24 PM