

## Utility Conflict Report

<b>OWNER</b>	<b>Utility</b>	SAWS	<b>Corridor</b>	SW MILITARY	<b>SITE PHOTOS</b>
	<b>Contact</b>	ANN PECHE	<b>ID</b>	4152	
<b>GENERAL INFO</b>	<b>Utility</b>	WATER			
	<b>Size and Material</b>	STANDARD WATER VALVE, CAST IRON			
	<b>Accessible Route</b>	ASSET IS INSIDE ACCESSIBLE ROUTE			
	<b>Longitudinal or Crossing</b>	CROSSING			
	<b>Placement Relative to ROW</b>	INSIDE ROW			
<b>LOCATION</b>	<b>Sheet No.</b>	156			
	<b>Station</b>	677+13.12			
	<b>Offset</b>	15.09			
	<b>Latitude</b>	+29.356548			
	<b>Longitude</b>	-98.51417			
<b>SUE</b>	<b>Level of Investigation Req'd</b>	NONE			
	<b>Test Hole No</b>	N/A			
	<b>Test Hole Depth</b>	N/A			
<b>RESOLUTION</b>	<b>Recommended Action</b>	NO CONFLICT			
	<b>Estimated Resolution Date</b>	10/3/2018			
	<b>Resolution Status</b>	NO RESOLUTION WAS REQUIRED			
	<b>Comment</b>	Valve to face of curb = 3'-11" Valve to back of curb = 1'-3" Sidewalk width = 5'-9 1/2" Top of valve to surface = 2'-7 1/2" Lid flange thickness = 2" Total lid thickness = 3 3/8"			
	<b>Date Collected</b>		8/1/2018 1:51:35 PM	<b>Date Modified</b>	

