PAPE-DAWSON ENGINEERS

Pavement Report

GENERAL INFO

ID	230
Corridor	BS 123B
Latitude	+29.581822
Longitude	-97.964896
Google Maps Hyperlink	http://local.google.com/maps?q=+29.581822,-97.964896
Field Notes	Full Width at Pine St 15' back FOC And 15'X12' patch

UTILITY DETAILS

Utility	Pavement Repair
Owner	TXDOT
Type	Vertical

SITE PHOTOS

Photo 1

Photo 2

Photo 3

Date Collected	11/8/2017 9:08 AM	**Date Modified**	12/11/2017 12:12:38