

Utility Conflict Report

OWNER	Utility	TIME WARNER	Corridor	RIGSBY	SITE PHOTOS
	Contact	FRANK CYPRIAN	ID	233	
GENERAL INFO	Utility	COMMUNICATIONS			
	Size and Material	OVERHEAD TELECOMM LINES			
	Utility Conflict Description	LINES TO BE RELOCATED WITH POLE RELOCATION			
	Longitudinal or Crossing	LONGITUDINAL			
	Placement Relative to ROW	INSIDE			
LOCATION	Sheet No.	326			
	Station Origin				
	Start Station	659+97.03	End Station		
	Start Offset	8.77	End Offset		
	Latitude	29.398167925	Longitude	-98.435556550000001	
SUE	Level of Investigation Req'd	NONE			
	Test Hole No	N/A			
	Test Hole Depth	N/A			
RESOLUTION	Recommended Action	ACCOMODATE - RELOCATION			
	Estimated Resolution Date				
	Resolution Status	UTILITY COORDINATION IN PROGRESS			
	Comment	RELOCATE LINES IN CONJUNCTION WITH POWER POLE RELOCATION, SEE CONFLICT ID 2073 FOR POLE RELOCATION			
Date Collected		10/4/2017 4:39:58 PM	Date Modified		11/30/2017 8:34:08 AM

