



## Pavement Report

<b>GENERAL INFO</b>	<p><b>ID</b>                    150</p> <p><b>Corridor</b>            BS 123B</p> <p><b>Latitude</b></p> <p><b>Longitude</b></p> <p><b>Google Maps Hyperlink</b></p> <p><b>Field Notes</b></p>
<b>UTILITY DETAILS</b>	<p><b>Utility</b>                Pavement Repair</p> <p><b>Owner</b>                TXDOT</p> <p><b>Type</b>                  Vertical</p>
<b>SITE PHOTOS</b>	<div style="display: flex; justify-content: space-around; margin-bottom: 20px;"> <span><b>Photo 1</b></span> <span><b>Photo 2</b></span> <span><b>Photo 3</b></span> </div> This area is intentionally left blank for photo uploads
<p><b>Date Collected</b>    11/7/2017 11:59:23 AM    <b>Date Modified</b>        12/11/2017 12:12:38</p>	

TBPE Firm Registration #470 | TBPLS Firm Registration #10028800

San Antonio | Austin | Houston | Fort Worth | Dallas  
 Transportation | Water Resources | Land Development | Surveying | Environmental

2000 NW Loop 410, San Antonio, TX 78213 T: 210.375.9000 www.Pape-Dawson.com