



Utility Conflict Report

OWNER	Utility	CPS	Corridor	BANDERA	SITE PHOTOS	
	Contact	JAKE MARTINEZ	ID	8002		
GENERAL INFO	Utility	ELECTRIC				
	Size and Material	STANDARD POWER POLE, TIMBER				
	Accessible Route	ASSET IS INSIDE ACCESSIBLE ROUTE				
	Longitudinal or Crossing	CROSSING				
	Placement Relative to ROW	INSIDE ROW				
LOCATION	Sheet No.					
	Station	N/A				
	Offset	N/A				
	Latitude					
	Longitude					
SUE	Level of Investigation Req'd	NONE				
	Test Hole No	N/A				
	Test Hole Depth	N/A				
RESOLUTION	Recommended Action	ACCOMODATE - RELOCATION				
	Estimated Resolution Date					
	Resolution Status	UTILITY OWNER INFORMED OF UTILITY				
	Comment	Bandera corridor has not yet been surveyed This record is a placeholder and is not a confirmed utility conflict				
Date Collected		Date Modified		8/17/2018 3:17:37 PM		

TBPE Firm Registration #470 | TBPLS Firm Registration #10028800