

## Pavement Report

|  |  |
|--|--|
| <b>GENERAL INFO</b>  | <p><b>ID</b>                    194</p> <p><b>Corridor</b>            BS 123B</p> <p><b>Latitude</b>            +29.576977</p> <p><b>Longitude</b>          -97.964804</p> <p><b>Google Maps<br/>Hyperlink</b>    <a +29.576977,-97.964804"="" href="http://local.google.com/maps?q=">http://local.google.com/maps?q="+29.576977,-97.964804</a></p> <p><b>Field Notes</b>        9'x4'</p>   |
| <b>UTILITY<br/>DETAILS</b>   | <p><b>Utility</b>                Pavement Repair</p> <p><b>Owner</b>                TXDOT</p> <p><b>Type</b>                    Vertical</p>   |
| <b>SITE PHOTOS</b>   | <div style="display: flex; justify-content: space-around;"> <div style="text-align: center;"> <p><b>Photo 1</b></p>  </div> <div style="text-align: center;"> <p><b>Photo 2</b></p>  </div> <div style="text-align: center;"> <p><b>Photo 3</b></p>  </div> </div> |
| <p><b>Date Collected</b>    11/7/2017 3:14 PM                      <b>Date Modified</b>        12/11/2017 12:12:38</p> |  |