



## Field Report

|   |  |
|---|--|
| <b>GENERAL INFO</b>   | <p><b>ID</b> 215</p> <p><b>Corridor</b> BS 123B</p> <p><b>Latitude</b> +29.579800</p> <p><b>Longitude</b> -97.964820</p> <p><b>Google Maps Hyperlink</b> <a +29.579800,-97.964820"="" href="http://local.google.com/maps?q=">http://local.google.com/maps?q="+29.579800,-97.964820</a></p> <p><b>Field Notes</b> Possible gas line - pave dips</p>   |
| <b>UTILITY DETAILS</b>  | <p><b>Utility</b> Unknown</p> <p><b>Owner</b> Question</p> <p><b>Type</b> Horizontal and Vertical</p>  |
| <b>SITE PHOTOS</b>  | <div style="display: flex; justify-content: space-around;"> <div style="text-align: center;"> <p><b>Photo 1</b></p>  </div> <div style="text-align: center;"> <p><b>Photo 2</b></p>  </div> <div style="text-align: center;"> <p><b>Photo 3</b></p>  </div> </div> |
| <p><b>Date Collected</b> 11/7/2017 4:22:04 PM      <b>Date Modified</b> 12/11/2017 12:12:38</p> |  |