

Utility Conflict Report

OWNER	Utility	SAWS	Corridor	SW MILITARY	SITE PHOTOS		
	Contact	ANN PECHE	ID	4105			
GENERAL INFO	Utility	WATER					
	Size and Material	STANDARD WATER VALVE, CAST IRON					
	Accessible Route	ASSET IS INSIDE ACCESSIBLE ROUTE					
	Longitudinal or Crossing	CROSSING					
	Placement Relative to ROW	INSIDE ROW					
LOCATION	Sheet No.	130					
	Station	539+55.11					
	Offset	14.52					
	Latitude	+29.357964					
	Longitude	-98.55735					
SUE	Level of Investigation Req'd	NONE					
	Test Hole No	N/A					
	Test Hole Depth	N/A					
RESOLUTION	Recommended Action	MINIMIZE - PROTECT IN PLACE					
	Estimated Resolution Date						
	Resolution Status	UTILITY OWNER INFORMED OF UTILITY					
	Comment	Back of curb to valve = 1'-7.5" Sidewalk width = 7'-5" Back of sidewalk to valve = 5'-1" Unable to open lid					
Date Collected		7/23/2018 12:10:22 PM		Date Modified		11/28/2018 6:59:12 AM	

