

Utility Conflict Report

OWNER	Utility	CPS	Corridor	SW MILITARY	SITE PHOTOS
	Contact	JAKE MARTINEZ	ID	4136	
GENERAL INFO	Utility	ELECTRIC			
	Size and Material	STANDARD POWER POLE, TIMBER			
	Accessible Route	ASSET IS INSIDE ACCESSIBLE ROUTE			
	Longitudinal or Crossing	CROSSING			
	Placement Relative to ROW	INSIDE ROW			
LOCATION	Sheet No.	150			
	Station	654+50.03			
	Offset	19.1502			
	Latitude	+29.356499			
	Longitude	-98.52143			
SUE	Level of Investigation Req'd	NONE			
	Test Hole No	N/A			
	Test Hole Depth	N/A			
RESOLUTION	Recommended Action	NO CONFLICT			
	Estimated Resolution Date				
	Resolution Status	NO RESOLUTION WAS REQUIRED			
	Comment	Pole ID: 432259 Pole to face of curb = 4'-3" Pole to face of wall = 4'-6" Back of curb to face of wall = 10'-0" CPS cannot move pole, will move curb to achieve 4' clearance			
Date Collected		8/1/2018 9:02:58 AM		Date Modified 12/18/2018 3:27:15 PM	

