

Utility Conflict Report

OWNER	Utility	SAWS	Corridor	SW MILITARY	SITE PHOTOS
	Contact	ANN PECHE	ID	7022	
GENERAL INFO	Utility	WATER			
	Size and Material	STANDARD WATER METER, CAST IRON			
	Accessible Route	ASSET IS OUTSIDE ACCESSIBLE ROUTE			
	Longitudinal or Crossing	CROSSING			
	Placement Relative to ROW	INSIDE ROW			
LOCATION	Sheet No.	213			
	Station	955+29.08			
	Offset	-26.0558			
	Latitude	+29.356879			
	Longitude	-98.49910			
SUE	Level of Investigation Req'd	NONE			
	Test Hole No	N/A			
	Test Hole Depth	N/A			
RESOLUTION	Recommended Action	MINIMIZE - PROTECT IN PLACE			
	Estimated Resolution Date				
	Resolution Status	UTILITY OWNER INFORMED OF UTILITY			
	Comment	Top of meter to surface = 7" Meter adjacent to edge of sidewalk Unknown pvc pipe adjacent to meter - full of dirt			
Date Collected		8/2/2018 4:15:40 PM	Date Modified		12/18/2018 8:55:09 AM

