

Utility Conflict Report

OWNER	Utility	UNKNOWN	Corridor	SW MILITARY	SITE PHOTOS		
	Contact	UNKNOWN	ID	7147			
GENERAL INFO	Utility	COMMUNICATIONS					
	Size and Material	UNKNOWN					
	Accessible Route	ASSET IS OUTSIDE ACCESSIBLE ROUTE					
	Longitudinal or Crossing	CROSSING					
	Placement Relative to ROW	INSIDE ROW					
LOCATION	Sheet No.	172					
	Station	755+76.64					
	Offset	-24.0125					
	Latitude	+29.358596					
	Longitude	-98.56156					
SUE	Level of Investigation Req'd	NONE					
	Test Hole No	N/A					
	Test Hole Depth	N/A					
RESOLUTION	Recommended Action	NO CONFLICT					
	Estimated Resolution Date						
	Resolution Status	NO RESOLUTION WAS REQUIRED					
	Comment	In-ground telecommunications box Back of sidewalk to utility box = 1'-7" Bottom of utility box to surface = 1'-0" Lid thickness = 2 3/4"					
Date Collected		8/6/2018 1:59:47 PM		Date Modified		11/28/2018 6:59:12 AM	

