

Utility Conflict Report

OWNER	Utility	SAWS	Corridor	NOGALITOS	SITE PHOTOS
	Contact	NINA BITTLE	ID	3035	
GENERAL INFO	Utility	WATER			
	Size and Material	STANDARD WATER METER, STEEL			
	Accessible Route	ASSET IS OUTSIDE ACCESSIBLE ROUTE			
	Longitudinal or Crossing	CROSSING			
	Placement Relative to ROW	INSIDE ROW			
LOCATION	Sheet No.				
	Station	130+57.70			
	Offset	-30.6046			
	Latitude	+29.392891			
	Longitude	-98.51843			
SUE	Level of Investigation Req'd	NONE			
	Test Hole No	N/A			
	Test Hole Depth	N/A			
RESOLUTION	Recommended Action	NO CONFLICT			
	Estimated Resolution Date	8/13/2018			
	Resolution Status	NO RESOLUTION WAS REQUIRED			
	Comment	Back of sidewalk to meter = 8 1/2" Unable to open rubber lid			
Date Collected		7/10/2018 11:06:56 AM		Date Modified 8/14/2018 4:38:26 PM	

