

Utility Conflict Report

| | | | | | | | |
|-----------------------|-------------------------------------|--|-----------------|----------------------|--------------------|----------------------|--|
| OWNER | Utility | CPS | Corridor | NOGALITOS | SITE PHOTOS | | |
| | Contact | JAKE MARTINEZ | ID | 4075 | | | |
| GENERAL INFO | Utility | ELECTRIC | | | | | |
| | Size and Material | STANDARD POWER POLE, TIMBER | | | | | |
| | Accessible Route | ASSET IS INSIDE ACCESSIBLE ROUTE | | | | | |
| | Longitudinal or Crossing | CROSSING | | | | | |
| | Placement Relative to ROW | INSIDE ROW | | | | | |
| LOCATION | Sheet No. | | | | | | |
| | Station | 127+19.47 | | | | | |
| | Offset | 23.1763 | | | | | |
| | Latitude | +29.392118 | | | | | |
| | Longitude | -98.51902 | | | | | |
| SUE | Level of Investigation Req'd | NONE | | | | | |
| | Test Hole No | N/A | | | | | |
| | Test Hole Depth | N/A | | | | | |
| RESOLUTION | Recommended Action | NO CONFLICT | | | | | |
| | Estimated Resolution Date | 8/13/2018 | | | | | |
| | Resolution Status | NO RESOLUTION WAS REQUIRED | | | | | |
| | Comment | Pole marking: P1557 Conduit to face of wall = 3'-6" Adjacent to VIA bus stop no. 62626 | | | | | |
| Date Collected | | 7/10/2018 2:07:37 PM | | Date Modified | | 8/14/2018 4:38:26 PM | |

